



REPORT OF LOW VOLTAGE ELECTRICAL INSTALLATION INSPECTION (RGIE)



Installation Address: [REDACTED], Grand-Rosière, Belgium
 Property Type: Manor on 3 levels with cellars and 2nd floor under roof (storage)
 Surface: 350m² habitable
 PEB: A

Characteristics

Meter: 3x400V+N
 Panels: 3 (Main Ground Floor, Div. Floor 1, Div. Cellars/Pool)
 Earth: < 30 Ohms OK
 RGIE Inspection: Compliant
 LV Inspection: 3 (Main Ground Floor, Div. Floor 1)
 Earth: < 30 Ohms OK
 Installation Number:

Visual Inspection and Measurements

Installation Inspection:	<input checked="" type="checkbox"/> Compliant
Meter/Connection Inspection:	<input checked="" type="checkbox"/> Compliant
Cellars:	<input checked="" type="checkbox"/> Compliant
Attic:	<input checked="" type="checkbox"/> Compliant
Attic (storage):	<input checked="" type="checkbox"/> Compliant
Swimming Pool:	<input checked="" type="checkbox"/> Compliant
Insulation Resistance Check:	<input checked="" type="checkbox"/> Compliant
Loop & Circuit Measurement:	<input checked="" type="checkbox"/> Compliant
Office Inspection:	<input checked="" type="checkbox"/> Compliant
Exterior Fixture Mounting:	<input checked="" type="checkbox"/> Compliant

Conclusion

The installation **IS COMPLIANT**

The installation **IS confirme** conclusùre au troit de les contradions méthalise sen contrôles et à la électrique-la installation électrique.

Le prouriis-values confiror du canvihe-r-aradeur, incompreton 'emamente ta: maianoe par la miasure de la expression entracteours au des 5 d'eit sut poccès visen le contrôle sur l'installation électrique.

Inspector :

Date : 24/02/2026

